

CA-1 lite and CA-2 lite spare hood

Headgear and connector manual

1



1. New pack
2. Connect the visor to the head band
3. Connect the visor on both sides
4. Turn the hood inside out
5. Turn the hood inside out
6. Connect the strap on both sides - second hole
7. Connector edge
8. Insert from inside to outside
9. Insert from inside to outside
10. Attach the connector ring
11. Click

2



3



4



